

ENERGY STAR[®] Statement of Energy Performance



Historical Museum

Primary Property Type: Museum Gross Floor Area (ft2): 834

Built: 1870

ENERGY STAR® Score¹

For Year Ending: August 31, 2016 Date Generated: October 28, 2016

1. The ENERGY STAR score is a 1-100 assessment of a building's energy efficiency as compared with similar buildings nationwide, adjusting for climate and business activity.

Property & Contact Information

Property Address Historical Museum P.O. Box 11

Knox, New York 12107

Property Owner Town of Knox 2192 Berne-Altamont Road

Knox, NY 12107 5188722551

Primary Contact Richard Weltzin 2192 Berne-Altamont Road

Knox, NY 12107 5188722551

benchmarkingknox@gmail.com

85.1

-95%

0

Property ID: 5083038

Source EUI

3.9 kBtu/ft²

Energy	Consumptio	n and Energy	Use Intensity	/ (EUI)

Annual Energy by Fuel Site EUI

Electric - Grid (kBtu) 1,038 (100%) 1.2 kBtu/ft²

National Median Comparison National Median Site EUI (kBtu/ft²) National Median Source EUI (kBtu/ft²) % Diff from National Median Source EUI

Annual Emissions

Greenhouse Gas Emissions (Metric Tons

CO2e/year)

Signature & Stamp of Verifying Professional

(Name) verify that the above information is true and correct to the best of my knowledge.			
Signature:	Date:		
Licensed Professiona	ય		
, ()			

Professional Engineer Stamp (if applicable)